



VEHICLE INSPECTION REPORT

CA15FMK

BMW 3 Series 335d xDrive M Sport 5dr Step Auto [Business Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/06/2015	Keys	2	CAP Average	£5,075.00
Year	2015	Service history	Yes	CAP Below	£4,325.00
Mileage	107,444 Miles Warranted	Number of stamps	4	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Last service date	05/10/2024	Gears	8
Colour	BLUE	Last service miles	89,830	Doors	5
VIN	WBA3Z92070D862870	MOT Due	30/06/2027		
Body Style	Hatchback	CAP Clean	£5,850.00		


Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		


Features

- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos



Condition Check




Damage Photos




1: Wheel osf
Scratched
Up To 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Dented
Over 30mm



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear
Dented
With Paint Damage




8: Tailgate
Dented
Over 30mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door nsf
Chipped
Edge Chip



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Bonnet
Dented
2 Or Less UpTo 10mm



18: Other
N/A
N/A



19: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK