



VEHICLE INSPECTION REPORT

RO69VTG

Nissan Qashqai 1.5 dCi 115 N-Connecta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/09/2019	Body Style	Hatchback	Last service miles	41,896
Year	2019	Keys	1	MOT Due	28/10/2026
Mileage	68,563 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	4	Doors	5
VIN	SJNFAAJ11U2494891	Last service date	21/09/2023		

Last service 21/09/2023 at 41,896 miles- 4 main dealer services Engine rattle on start up


Tyres		
NSF	MICHELIN	3.0mm
NSR	KUMHO	6.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
Edge Chip



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Chipped
Multiple Chips




11: Door osr
Dented
Between 10mm + 30mm



12: Door osf
Chipped
Edge Chip



13: Door osf
Dented
2 Or Less UpTo 10mm



14: Wing osf
Scratched
UpTo 25mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK