



VEHICLE INSPECTION REPORT

LC65BWL

Volvo XC60 D4 [190] SE Lux Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/11/2015	Body Style	Estate	Last service miles	94,818
Year	2015	Keys	2	MOT Due	Expired
Mileage	100,831 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	GOLD	Number of stamps	6	Doors	5
VIN	YV1DZA8C1G2854654	Last service date	04/08/2025		

MOT EXPIRED

LAST SERVICE 04/08/2025 @ 94,818 MILES (6 SERVICES) Noisy engine

Noisy clutch

Steering knocking

Tyres


NSF	KUMHO	6.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	6.0mm
OSR	AVON	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: A Post ns
Rusted
Over 5mm



7: Door nsf
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Thru Paint




9: Qtr Panel nsr
Dented
Between 10mm + 30mm




10: Qtr Panel nsr
Chipped
1 To 5



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Over 50mm



15: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



16: Door osr
Poor Previous Repair
Poor Paint



17: Door osf
Chipped
Edge Chip



18: Wheel osf
Scratched
Over 50mm



19: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK