



VEHICLE INSPECTION REPORT

GU70WHC

BMW 3 Series 330e M Sport 4dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/10/2020	Keys	2	CAP Clean	£12,850.00
Year	2020	Service history	Yes	CAP Average	£11,700.00
Mileage	82,402 Miles Warranted	Service documents	Printout	CAP Below	£10,600.00
Fuel Type	HYBRID ELECTRIC	Number of stamps	3	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	19/07/2024	Gears	8
VIN	WBA5P52090FK17150	Last service miles	40,183	Doors	4
Body Style	Saloon	MOT Due	21/01/2027		

LAST SERVICE 19/07/2024 @ 40,183 MILES (3 SERVICES, 3 MAIN DEALER) Power supply warning displayed
Drivetrain warning displayed
Electric drive restricted message displayed
Type 2 and 3 pin charging cables
Power steering warning light displayed

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	FIRESTONE	5.0mm
OSF	BRIDGESTONE	6.0mm
OSR	FIRESTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking


Photos







Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5




4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Chipped
1 To 5



8: Wheel nsr
Corroded
Light



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Door nsf
Chipped
Edge Chip




11: Wing nsf
Chipped
1 To 5



12: Wheel nsf
Corroded
Light



13: Bumper Front Grill
Broken
Replace



14: Bumper Front
Cracked
UpTo 25mm



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK