



# VEHICLE INSPECTION REPORT

**KH05YYD**

## Ford Fiesta 1.4 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	10/06/2005	Keys	2	CAP Clean	£350.00
Year	2005	Service history	Yes	CAP Average	£200.00
Mileage	85,165 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLUE	Last service date	11/09/2023	Gears	5
VIN	WF0HXXWPJH5P02600	Last service miles	78,203	Doors	5
Body Style	Hatchback	MOT Due	16/09/2025		

£50 ADDITIONAL FEE. Last Service: 11/09/2023 at 78203 miles. (10 services (1 main dealer)) Squeaky belt and bonnet latch broken

### Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- PAS
- Air conditioning
- Rear headrests
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Climate control
- Metallic Paint
- Passenger airbag
- Steel wheels
- Radio/CD
- Front electric windows
- 3x3 point rear seat belts
- Central locking
- Body coloured bumpers
- Front head restraints
- ABS
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Cracked  
Over 25mm





3: Wing nsf  
Chipped  
1 To 5



4: Door nsf  
Poor Previous Repair  
Poor Paint



5: Door nsr  
Dented  
With Paint Damage



6: Qtr Panel osr  
Chipped  
1 To 5



7: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint




8: Bumper Rear  
Poor Previous Repair  
Rippled Up To 30%



9: Boot Lid  
Dented  
Over 30mm

No Image

10: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



11: Door osr  
Scratched  
UpTo 25mm Thru Paint

No Image

12: Door osr  
Scratched  
Over 25mm Not Thru Paint



13: Door osf  
Dented  
Over 2 UpTo 10mm

No Image

14: Door osf  
Scratched  
Over 25mm Not Thru Paint






15: Door Moulding osf  
Missing  
Replace



16: Wing osf  
Chipped  
1 To 5



17: Wing osf  
Scratched  
Over 25mm Not Thru Paint



18: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK