



VEHICLE INSPECTION REPORT

BF66PUA

Vauxhall Astra 1.4T 16V 150 SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2017	Body Style	Hatchback	MOT Due	30/01/2027
Year	2017	Service history	Yes	Gearbox	MANUAL
Mileage	104,012 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	PETROL	Number of stamps	8	Doors	5
Colour	GREY	Last service date	20/01/2025		
VIN	W0LBF6EC1HG081749	Last service miles	90,352		

£100 ADDITIONAL FEE

Last Service - 20.01.2025 at 90352 miles (8 services)

Tyres


NSF	FALKEN	2.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	2.0mm
OSR	TRIANGLE	6.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alarm
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: A Post os
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Bumper Rear
Chipped
1 To 5



10: Door nsr
Chipped
Multiple Chips



11: Door nsf
Chipped
Multiple Chips



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bumper Front
Chipped
Multiple Chips



15: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK