



# VEHICLE INSPECTION REPORT

**LB17BJV**

## Vauxhall Zafira 1.4T SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	16/06/2017	Keys	1	CAP Clean	£3,125.00
Year	2017	Service history	Yes	CAP Average	£2,675.00
Mileage	110,964 Miles Warranted	Service documents	Printout	CAP Below	£2,150.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	GREEN	Last service date	15/03/2024	Gears	6
VIN	W0LPD9EC6H1084985	Last service miles	96,481		
Body Style	MPV	MOT Due	Expired		

Last Service - 15.03.2024 at 96481 miles ( 5 services)

### Tyres

NSF	SUNNY	4.0mm
NSR	SUNNY	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





Condition Check



Damage Photos



1: Other  
N/A  
N/A




2: Wheel osf  
Scratched  
Over 50mm





3: Wing osf  
Dented  
2 Or Less UpTo 10mm



4: Door osf  
Scratched  
Over 25mm Thru Paint



5: Door osr  
Chipped  
1 To 5



6: Wheel osr  
Scratched  
Over 50mm




7: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



8: Qtr Panel osr  
Scratched  
UpTo 25mm Not Thru Paint





9: Bumper Rear  
Scratched  
Over 100mm Thru Paint




10: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



11: Wheel nsr  
Scratched  
Over 50mm



12: Door nsr  
Scratched  
Over 25mm Not Thru Paint



13: Door nsf  
Chipped  
1 To 5



14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint





15: Wheel nsf  
Scratched  
Over 50mm



16: Bonnet  
Chipped  
Multiple Chips



17: Bumper Front  
Scratched  
Over 100mm Thru Paint

### Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

### Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK