



VEHICLE INSPECTION REPORT

GN69KTT

Mazda CX-5 2.0 GT Sport Nav+ 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	13/09/2019	Body Style	Estate	Last service miles	74,019
Year	2019	Keys	2	MOT Due	25/04/2027
Mileage	115,620 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	JMZKF6W7A00867048	Last service date	10/04/2024		

£90 ADDITIONAL FEE

Last Service - 10.04.24 at 74019 miles (5 main dealer services)


Tyres		
NSF	TOYO	3.0mm
NSR	TOYO	5.0mm
OSF	TOYO	3.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Corroded
Light



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Scratched
Up To 25mm Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Tailgate
Chipped
1 To 5



10: Wheel osr
Corroded
Light



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Wing osf
Scratched
UpTo 25mm Thru Paint



14: Wheel osf
Scratched
Up To 50mm



15: Tailgate Trim Panel
Scratched (Painted)
Over 25mm Thru Paint



16: Bumper Front
Dented
With Paint Damage



17: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		