



VEHICLE INSPECTION REPORT

EX60KPF

Volkswagen Golf 1.4 S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/09/2010	Body Style	Hatchback	Last service miles	132,754
Year	2010	Keys	2	MOT Due	01/10/2026
Mileage	137,298 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	6	Doors	5
VIN	WVWZZZ1KZAW386092	Last service date	03/10/2025		

LAST SERVICE 03/10/2025 @ 132,754 MILES (6 SERVICES) Rattle from engine, spongy brake

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	SUNNY	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Trip computer
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Alarm

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Dented
With Paint Damage




4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: A Post ns
Chipped
1 To 5



7: Door nsf
Poor Previous Repair
Rippled UpTo 30%



8: Handle Outer nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Sill ns
Dented
With Paint Damage



10: Door nsr
Poor Previous Repair
Poor Paint



11: Door nsr
Scratched
Over 25mm Thru Paint




12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
Over 100mm Thru Paint




15: Bumper Rear
Poor Previous Repair
Poor Paint



16: Qtr Panel osr
Chipped
1 To 5



17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Chipped
1 To 5



19: Door osr
Scratched
Over 25mm Thru Paint



20: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint



21: Door osf
Chipped
Multiple Chips



22: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



23: A Post os
Chipped
1 To 5



24: Roof
Chipped
Edge Chip



25: Wing osf
Scratched
Over 25mm Thru Paint



26: Wheel osf
Scratched
Over 50mm



27: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK