



VEHICLE INSPECTION REPORT

FP74KSX

Dacia Jogger 1.0 TCe Extreme 5dr

Cat: S Incident History

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present



Details

Reg. date	05/11/2024	VIN	UU1DJF00773826840	Gearbox	MANUAL
Year	2024	Body Style	MPV	Gears	6
Mileage	16,023 Miles Warranted	Keys	1	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	BROWN	MOT Due	14/01/2027		

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair
NO SERVICE HISTORY Car shake when idle

Tyres


NSF	HANKOOK	3.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
 - Navigation system
 - Rear wiper
 - Body coloured bumpers
 - Air conditioning
 - Front head restraints
 - Steering wheel rake adjustment
 - ABS
 - Side airbags
 - Cloth seat trim
- Cruise control
 - Park assist camera
 - Service indicator
 - Electric door mirrors
 - Folding rear seats
 - Height adjustable drivers seat
 - Steering wheel reach adjustment
 - Drivers airbag
 - Tyre pressure monitor
 - Alloy wheels
- Front parking sensor
 - PAS
 - Steering wheel mounted controls
 - Front fog lights
 - Front armrest
 - Rear electric windows
 - Metallic Paint
 - Isofix child seat anchor points
 - Central locking
- Heated front seat
 - Rear parking sensor
 - Digital radio
 - Roof rails
 - Front electric windows
 - Rear headrests
 - 3x3 point rear seat belts
 - Passenger airbag
 - Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
Over 25mm Thru Paint



5: A Post ns
Chipped
1 To 5



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Tailgate
Dented
2 Or Less UpTo 10mm



13: Tailgate
Chipped
1 To 5




14: Roof
Dented
Over 30mm




15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Door osr
Dented
Over 30mm



18: Door osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK