



VEHICLE INSPECTION REPORT

SD63PPU

Lexus CT 200h 1.8 Advance 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2013	Body Style	Hatchback	Last service miles	76,069
Year	2013	Keys	2	MOT Due	21/09/2027
Mileage	76,483 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	BLACK	Number of stamps	10	Doors	5
VIN	JTHKD5BH202154774	Last service date	25/08/2026		

Last Service - 25.08.26 at 76069 miles (10 services)

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	Damaged
OSF	BUDGET	Damaged
OSR	BUDGET	Damaged
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Rusted



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip




7: Door nsf
Chipped
1 To 5




8: Door nsf
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door nsr
Chipped
Edge Chip



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Roof
Dented
Over 30mm



15: Qtr Panel osr
Poor Previous Repair
Poor Paint




16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osr
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Scratched
UpTo 25mm Thru Paint



22: Other
N/A
N/A



23: Tyre osf
Damaged
Replace



24: Tyre osr
Damaged
Replace



25: Tyre nsr
Damaged
Replace



26: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK