



VEHICLE INSPECTION REPORT

WM20HFA

Seat Ateca 1.5 TSI EVO FR Sport [EZ] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	20/08/2020	Keys	2	CAP Clean	£10,500.00
Year	2020	Service history	Yes	CAP Average	£9,275.00
Mileage	47,796 Miles Warranted	Service documents	Printout	CAP Below	£8,100.00
Fuel Type	PETROL	Number of stamps	3	Gearbox	MANUAL
Colour	BLACK	Last service date	21/08/2023	Gears	6
VIN	VSSZZZ5FZL6545434	Last service miles	16,006	Doors	5
Body Style	Hatchback	MOT Due	12/01/2027		

LAST SERVICE 21/08/2023 @ 16,006 MILES (3 SERVICES)

Tyres

NSF	CONTINENTAL	Damaged
NSR	BRIDGESTONE	4.0mm
OSF	KORMORAN	Damaged
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Qtr Panel Moulding ns
Scratched (Painted)
UpTo 25mm Thru Paint



11: Door nsr
Chipped
1 To 5



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
 Scratched
 Over 25mm Thru Paint



16: Roof
 Dented
 2 Or Less UpTo 10mm



17: Tyre osf
 Damaged
 Replace



18: Tyre nsf
 Damaged
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK