



VEHICLE INSPECTION REPORT

BT69FZA

Mercedes-Benz A Class A180d AMG Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/11/2019	Body Style	Hatchback	Last service miles	111,966
Year	2019	Keys	2	MOT Due	21/11/2026
Mileage	118,606 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	6	Doors	5
VIN	WDD1770032N143321	Last service date	23/03/2026		

Last Service - 23.03.26 at 111966 miles (6 services (5 main dealer)) Engine rattle when idle

Tyres

NSF	WESTLAKE	5.0mm
NSR	BUDGET	5.0mm
OSF	WESTLAKE	5.0mm
OSR	AVON	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Park assist camera
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: A Post ns
Chipped
1 To 5



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Edge Chip




8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Dented
Over 30mm



13: A Post os
Dented
Over 30mm



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Qtr Panel osr
Chipped
1 To 5



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Poor Previous Repair
Rippled Up To 30%



18: Door osf
Chipped
Edge Chip



19: Door osf
Poor Previous Repair
Poor Paint



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: A Post os
Chipped
1 To 5



23: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK