



VEHICLE INSPECTION REPORT

PX15OEJ

Citroen DS3 1.2 PureTech Dsign Plus 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2015	Body Style	Hatchback	Last service miles	23,034
Year	2015	Keys	2	MOT Due	26/02/2027
Mileage	81,796 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	1	Doors	3
VIN	VF7SAHMZ0FW535121	Last service date	14/07/2017		

£100 ADDITIONAL FEE

Last Service - 14.07.2017 at 23034 miles (1 Service)

Bonnet out of line

Tyres

NSF	SUNNY	5.0mm
NSR	RIKEN	3.0mm
OSF	SUNNY	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Door Pad osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Bumper Front Moulding
Missing
Replace



5: Bumper Front
Insecure
Action Required



6: Wing nsf
Dented
With Paint Damage



7: Wheel nsf
Scratched
Over 50mm




8: Door nsf
Chipped
1 To 5



9: Door nsf
Dented
Between 10mm + 30mm




10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



12: Bumper Rear
Dented
With Paint Damage




13: Wheel osr
Scratched
Over 50mm



14: Roof
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Door osf
Scratched
UpTo 25mm Thru Paint



17: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK