



VEHICLE INSPECTION REPORT

EN13TWU

Hyundai IX35 2.0 CRDi Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/07/2013	Keys	2	CAP Clean	£1,725.00
Year	2013	Service history	Yes	CAP Average	£1,275.00
Mileage	91,427 Miles Warranted	Service documents	Printout	CAP Below	£875.00
Fuel Type	DIESEL	Number of stamps	7	Gearbox	MANUAL
Colour	SILVER	Last service date	14/11/2025	Gears	6
VIN	TMAJU81VNDJ391925	Last service miles	84,898	Doors	5
Body Style	Estate	MOT Due	06/09/2027		

CLUTCH REPLACED 18/12/2023 @ 76,313 MILES

LAST SERVICE 14/11/2025 @ 84,898 MILES (7 SERVICES) Sunroof does not work

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Heated front seat
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Central locking
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
UpTo 25mm Thru Paint




4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		