



VEHICLE INSPECTION REPORT

GV18JYX

Mercedes-Benz GLA GLA 200d AMG Line 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	14/06/2018	Body Style	Estate	Last service miles	35,342
Year	2018	Keys	2	MOT Due	17/04/2027
Mileage	78,822 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	BLUE	Number of stamps	3	Doors	5
VIN	WDC1569082J525442	Last service date	09/08/2021		

£100 ADDITIONAL FEE

Last Service - 09.08.21 at 35342 miles (3 main dealer services) Eml light is on car been plugged in and detected- knock control at upper threshold

Tyres

NSF	ACCELERA	5.0mm
NSR	ACCELERA	5.0mm
OSF	ACCELERA	5.0mm
OSR	CONTINENTAL	Damaged
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Park assist camera
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Bumper Rear
Dented
With Paint Damage



9: Wheel nsr
Corroded
Light



10: Door nsr
Chipped
Edge Chip



11: Door nsr
Chipped
1 To 5



12: Door nsf
Chipped
1 To 5



13: Wing nsf
Chipped
Multiple Chips



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Scratched
25 to 100mm Thru Paint



16: Bonnet
Chipped
1 To 5



17: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK