



VEHICLE INSPECTION REPORT

GD18VGV

Audi A3 1.5 TFSI S Line 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	25/06/2018	Body Style	Saloon	Last service miles	86,901
Year	2018	Keys	2	MOT Due	13/03/2027
Mileage	93,535 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	7	Doors	4
VIN	WAUZZZ8V9J1079193	Last service date	06/03/2026		

£90 ADDITIONAL FEE

LAST SERVICE 06/03/2026 @ 86,901 MILES (7 SERVICES) Carpet soiled in boot

Tyres


NSF	TRIANGLE	5.0mm
NSR	TRIANGLE	5.0mm
OSF	TRIANGLE	Damaged
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Screen Front
Cracked
Replace



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Over 5mm




10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Poor Previous Repair
Rippled UpTo 30%



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Chipped
1 To 5



17: Seat Back Cover osf
Scuffed
Over 25mm



18: Roof
Chipped
1 To 5



19: Tyre osf
Damaged
Replace



20: Carpets Front
Soiled
Light

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK