



VEHICLE INSPECTION REPORT

GN66NSZ

Citroen C4 Picasso 1.6 BlueHDi Flair 5dr EAT6

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	01/09/2016	Body Style	MPV	Last service miles	19,378
Year	2016	Keys	2	MOT Due	09/09/2027
Mileage	50,039 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	5	Doors	5
VIN	VF73DBHZTGJ773381	Last service date	25/08/2021		

£90 ADDITIONAL FEE

LAST SERVICE 25/08/2021 @ 19,378 MILES (5 SERVICES)

Tyres

NSF	MICHELIN	2.0mm
NSR	PIRELLI	5.0mm
OSF	CONTINENTAL	2.0mm
OSR	ROTALLA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Headrest Assy Rear Seat os
Missing
Replace



2: Headrest Assy Rear Seat ns
Missing
Replace



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Cracked
Over 25mm



5: Parking Sensor Front
Missing
Replace



6: Bumper Front Moulding
Broken
Replace




7: Bumper Front Grill
Broken
Replace



8: Wheel nsf
Scratched
Over 50mm




9: Door nsf
Chipped
Edge Chip




10: Door nsf
Dented
Over 30mm



11: A Post ns
Scratched
UpTo 25mm Thru Paint



12: Door nsr
Poor Previous Repair
Rippled UpTo 30%



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Dented
Over 30mm



15: Bumper Rear
Cracked
Over 25mm



16: Tailgate
Scratched
UpTo 25mm Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Scratched
Over 25mm Thru Paint



20: Door osf
Chipped
Edge Chip



21: Wing osf
Chipped
1 To 5



22: Wheel osf
Scratched
Over 50mm



23: A Post os
Scratched
Over 25mm Thru Paint



24: A Post os
Dented
Between 10mm + 30mm



25: B Post os
Dented
Between 10mm + 30mm



26: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK