



VEHICLE INSPECTION REPORT

EA63WTL

Volkswagen Golf 1.6 TDI 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/12/2013	Body Style	Hatchback	MOT Due	03/08/2027
Year	2013	Service history	Yes	Gearbox	MANUAL
Mileage	137,758 Miles Warranted	Service documents	Printout	Gears	5
Fuel Type	DIESEL	Number of stamps	5	Doors	5
Colour	BLACK	Last service date	28/02/2025		
VIN	WVVZZZAUZEW184661	Last service miles	126,313		

£90 ADDITIONAL FEE

TIMING BELT & WATER PUMP REPLACED 27/02/2024

LAST SERVICE 28/02/2025 @ 126,313 MILES (5 SERVICES)

Tyres

NSF	LAUFENN	4.0mm
NSR	LAUFENN	2.0mm
OSF	LAUFENN	4.0mm
OSR	LAUFENN	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Alarm
- Cruise control
- PAS
- Trip computer
- Heated door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Climate control
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Wing of
Poor Previous Repair
Poor Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Bonnet
Chipped
1 To 5



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Poor Previous Repair
Paint Flake



6: Door nsr
Scratched
Over 25mm Thru Paint




7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osf
Poor Previous Repair
Poor Paint



11: Reflector nsr
Broken
Replace



12: Roof
Scratched
Over 25mm Thru Paint



13: Door osr
Poor Previous Repair
Poor Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		