



VEHICLE INSPECTION REPORT

GL66BMY

Kia Sportage 1.6 GDi 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2016	Body Style	Estate	Last service miles	18,949
Year	2016	Keys	1	MOT Due	30/10/2026
Mileage	100,678 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	3	Doors	5
VIN	U5YPG814LGL187944	Last service date	27/11/2019		

£90 ADDITIONAL FEE

Last Service - 27.11.2019 at 18949 miles (3 services)

Clutch Replaced 21.11.2024 @ 80322 Miles

Tyres

NSF	HANKOOK	2.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	2.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Dented
With Paint Damage




11: Bumper Reflector osr
Broken
Replace




12: Tailgate
Scratched
Over 25mm Thru Paint



13: Roof
Dented
Over 30mm



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osr
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
 Scratched
 UpTo 25mm Thru Paint



22: Switches And Controls
 Broken
 Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK