



VEHICLE INSPECTION REPORT

DP17WXH

Vauxhall Corsa 1.4 Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/06/2017	Body Style	Hatchback	MOT Due	29/07/2027
Year	2017	Keys	2	Gearbox	MANUAL
Mileage	96,015 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	PETROL	Service documents	Service Book	Doors	5
Colour	BLACK	Number of stamps	2		
VIN	W0L0XEP68H4277742	Last service date	21/01/2021		

£90 ADDITIONAL FEE

LAST SERVICE 21/01/2021 @ UNKNOWN MILES (2 SERVICES) Exhaust blowing

Tyres

NSF	INVOVIC	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Cloth seat trim
- Cruise control
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Steel wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Qtr Panel osr
Dented
Between 10mm + 30mm




12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: B Post os
Scratched
Over 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Scratched
Over 25mm Thru Paint



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Wing osf
Chipped
1 To 5



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK