



VEHICLE INSPECTION REPORT

MW62LDV

Volkswagen Polo 1.2 60 Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2013	Body Style	Hatchback	Last service miles	87,237
Year	2013	Keys	2	MOT Due	02/11/2026
Mileage	97,182 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	12	Doors	5
VIN	WVWZZZ6RZDU022897	Last service date	21/10/2025		

£90 ADDITIONAL FEE

LAST SERVICE 21/10/2025 @ 87,237 MILES (12 SERVICES) Exhaust blowing

Tyres


NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Bumper Front
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Sill ns
Rusted
Over 5mm



7: Sill ns
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Multiple Chips



9: Door nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear
Cracked
UpTo 25mm



13: Qtr Panel osr
Dented
Over 2 UpTo 10mm



14: Qtr Panel osr
Chipped
1 To 5




15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Between 10mm + 30mm




17: Door osr
Chipped
Multiple Chips



18: Door osf
Chipped
Multiple Chips



19: Door osf
Dented
2 Or Less UpTo 10mm




20: Roof
Dented
Between 10mm + 30mm



21: Wheel osf
Scratched
Over 50mm



22: Wing osf
Chipped
1 To 5



23: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK