



VEHICLE INSPECTION REPORT

GV17WBN

Suzuki Sx4 S-Cross 1.0 Boosterjet SZ-T 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/07/2017	Body Style	Hatchback	Last service miles	37,433
Year	2017	Keys	2	MOT Due	21/11/2026
Mileage	54,531 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6	Doors	5
VIN	TSMJYA02S00520839	Last service date	18/08/2023		

LAST SERVICE 18/08/2023 @ 37,433 MILES (6 SERVICES)

Tyres

NSF	WESTLAKE	5.0mm
NSR	SUNNY	5.0mm
OSF	BUDGET	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Other
N/A
N/A



5: A Post ns
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
Edge Chip



8: Door nsr
Chipped
1 To 5



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel nsr
Chipped
1 To 5



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
UpTo 25mm Thru Paint



14: Door osf
Dented
2 Or Less UpTo 10mm




15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Wheel osf
Scratched
Up To 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK