



VEHICLE INSPECTION REPORT

LD68RXJ

Land Rover Range Rover Sport 2.0 P400e HSE Dynamic 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/11/2018	Body Style	Estate	Last service miles	91,557
Year	2018	Keys	2	MOT Due	02/11/2026
Mileage	92,404 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	4	Doors	5
VIN	SALWA2AY9KA830165	Last service date	26/08/2026		

£90 ADDITIONAL FEE

LAST SERVICE 26/08/2026 @ 91,557 MILES (4 SERVICES)

Type 2 charging cable

SOS system limited functionality

Rear camera faulty

Tyres

NSF	BUDGET	5.0mm
NSR	SUNNY	5.0mm
OSF	TRIANGLE	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Dented
Over 30mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Other
N/A
N/A



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



13: Bumper Rear
Dented
With Paint Damage



14: Tailgate
Scratched
Over 25mm Thru Paint



15: Other
N/A
N/A



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door nsr
Chipped
1 To 5



19: Door osr
Dented
2 Or Less UpTo 10mm



20: Door osf
Dented
With Paint Damage



21: Door osr
Scratched
Over 25mm Thru Paint



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Screen Front
Cracked
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK