



VEHICLE INSPECTION REPORT

GY69ZHP

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	22/11/2019	Body Style	Hatchback	Last service miles	3,900
Year	2019	Keys	2	MOT Due	27/11/2026
Mileage	30,295 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	1	Doors	5
VIN	WVGZZC1ZLY034249	Last service date	20/08/2020		

£90 ADDITIONAL FEE

LAST SERVICE 20/08/2020 @ 3,900 MILES (1 SERVICE)


Tyres


NSF	BRIDGESTONE	2.0mm
NSR	DUNLOP	6.0mm
OSF	BRIDGESTONE	1.0mm
OSR	DUNLOP	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check




Damage Photos



1: Wheel osf
Scratched
Up To 50mm




2: Door osf
Poor Previous Repair
Poor Paint



3: A Post os
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Poor Previous Repair
Poor Paint



11: Door nsf
Dented
With Paint Damage



12: Wing nsf
Dented
Between 10mm + 30mm



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Poor Previous Repair
Poor Paint



15: Bonnet
Scratched
UpTo 25mm Thru Paint



16: Roof
Scratched
Over 25mm Thru Paint



17: Tailgate
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK