



VEHICLE INSPECTION REPORT

GF22TBX

Skoda Kodiaq 1.5 TSI SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/05/2022	Keys	2	CAP Clean	£12,150.00
Year	2022	Service history	Yes	CAP Average	£10,900.00
Mileage	79,451 Miles Warranted	Service documents	Printout	CAP Below	£9,750.00
Fuel Type	PETROL	Number of stamps	6	Gearbox	MANUAL
Colour	GREY	Last service date	26/03/2025	Gears	6
VIN	TMBKB7NS0N8032073	Last service miles	57,912	Doors	5
Body Style	Estate	MOT Due	01/04/2027		

£90 ADDITIONAL FEE

LAST SERVICE 23/03/2025 @ 57,912 (6 SERVICES, ALL MAIN DEALER) 5 seats

Tyres

NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



3: Door osf
Dented
Between 10mm + 30mm



4: Door osf
Chipped
Edge Chip



5: Door osr
Dented
2 Or Less UpTo 10mm



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Chipped
1 To 5



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Door nsr
Chipped
1 To 5



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Door nsf
Chipped
Edge Chip



13: Door nsf
Chipped
1 To 5



14: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Wing nsf
Chipped
1 To 5



16: Wheel nsf
Scratched
Up To 50mm



17: Bumper Front
Dented
With Paint Damage



18: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK