



VEHICLE INSPECTION REPORT

OIG4849

Vauxhall Corsa 1.4T [100] Limited Edition 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2015	Keys	2	CAP Clean	£2,675.00
Year	2015	Service history	Yes	CAP Average	£2,250.00
Mileage	77,450 Miles Warranted	Service documents	Service Book	CAP Below	£1,800.00
Fuel Type	PETROL	Number of stamps	1	Gearbox	MANUAL
Colour	WHITE	Last service date	15/01/2016	Gears	6
VIN	W0LOXEP08F6056146	Last service miles	5,754	Doors	3
Body Style	Hatchback	MOT Due	Expired		

MOT EXPIRED

LAST SERVICE 15/01/2016 @ 5,754 MILES (1 SERVICE) Eml light is on car been plugged in and detected system too lean bank 1

Tyres

NSF	BUDGET	5.0mm
NSR	TRIANGLE	4.0mm
OSF	TRIANGLE	2.0mm
OSR	COMFORSER	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Sill Panel Trim ns
Broken
Replace



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Bumper Rear
Dented
With Paint Damage



10: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



11: Door nsf
Dented
Over 30mm



12: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



13: Wheel osr
Scratched
Up To 50mm




14: Door osf
Dented
With Paint Damage



15: Wing osf
Dented
Over 30mm



16: Wheel osf
Scratched
Over 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Scratched
Over 25mm Thru Paint



19: Seat Base Cover osf
Torn
Over 3mm



20: Tailgate
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK