



VEHICLE INSPECTION REPORT

GX65ZZY

Vauxhall Viva 1.0 ecoFLEX SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/09/2015	Body Style	Hatchback	Last service miles	62,646
Year	2015	Keys	2	MOT Due	01/09/2027
Mileage	62,901 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	8	Doors	5
VIN	W0LDD6E78GC517472	Last service date	27/08/2026		

Last Service - 27.08.26 at 62646 miles (8 services)


Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Cruise control
- Media storage
- Front electric windows
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels
- PAS
- Body coloured bumpers
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wheel Trim nsf
Broken
Replace




4: Wing nsf
Chipped
1 To 5



5: Door nsf
Poor Previous Repair
Rippled UpTo 30%



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Door nsr
Chipped
Multiple Chips



8: Door nsr
Poor Previous Repair
Rippled UpTo 30%



9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint




12: Wheel Trim osr
Missing
Replace



13: Qtr Panel osr
Chipped
1 To 5




14: Door osr
Poor Previous Repair
Rippled UpTo 30%



15: Door osf
Chipped
Edge Chip



16: Door osf
Dented
With Paint Damage



17: Wing osf
Chipped
1 To 5



18: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK