



VEHICLE INSPECTION REPORT

GY12KFT

BMW 3 Series 320d SE 4dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/04/2012	Body Style	Saloon	Last service miles	103,513
Year	2012	Keys	2	MOT Due	28/05/2027
Mileage	108,450 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	7	Doors	4
VIN	WBA3D32060FK57528	Last service date	13/05/2025		

£90 ADDITIONAL FEE

LAST SERVICE 13/05/2025 @ 103,513 MILES (7 SERVICES) Engine noisy car shake while idle

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Traction control
- Alloy wheels
- Heated front seat
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Screen Front
Chipped
Over 10mm



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Other
N/A
N/A



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
2 Or Less UpTo 10mm



17: Door osr
Chipped
1 To 5



18: Door osf
Chipped
Edge Chip



19: Door osf
Dented
Between 10mm + 30mm



20: Wing osf
Dented
Between 10mm + 30mm




21: Wing osf
Scratched
Over 25mm Thru Paint



22: Wheel osf
Scratched
Over 50mm



23: A Post os
Scratched
UpTo 25mm Thru Paint



24: Seat Back Cover osf
Scuffed
Over 25mm



25: Door Pad osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK