



VEHICLE INSPECTION REPORT

EX11HOJ

Hyundai I30 1.4 Comfort 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/03/2011	Body Style	Hatchback	Last service miles	63,132
Year	2011	Keys	2	MOT Due	15/07/2027
Mileage	81,660 Miles Not Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	11	Doors	5
VIN	TMADB51CLBJ193979	Last service date	25/04/2024		

Last Service - 25.04.24 at 63132 miles (11 services)
Speedo Change in 2013 @26869 Exhaust blowing

Tyres




NSF	DAVANTI	5.0mm
NSR	BUDGET	5.0mm
OSF	DAVANTI	5.0mm
OSR	DAVANTI	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Fascia Trim
Missing
Replace



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm




5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Thru Paint



7: A Post ns
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Rusted



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
Between 10mm + 30mm



13: Door nsf
Dented
Over 30mm



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Chipped
1 To 5



20: Screen Front
Chipped
Over 10mm



21: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK