



VEHICLE INSPECTION REPORT

KO16WMX

Nissan Qashqai 1.6 dCi N-Connecta 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
4

Details

Reg. date	01/07/2016	Colour	BLACK	MOT Due	01/03/2027
Year	2016	VIN	SJNFDAJ11U1741807	Gearbox	CVT
Mileage	90,434 Miles Warranted	Body Style	Hatchback	Gears	1
Fuel Type	DIESEL	Keys	2	Doors	5

Tyres


NSF	KUMHO	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	KUMHO	4.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Other
N/A
N/A



4: Bumper Front
Scratched
25 to 100mm Thru Paint




5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5




8: Screen Front
Chipped
UpTo 10mm



9: Door nsf
Dented
Between 10mm + 30mm



10: Door nsf
Chipped
Edge Chip



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



15: Bumper Rear
Scratched
Up To 25mm Thru Paint



16: Tailgate
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Scratched
Over 25mm Thru Paint



20: B Post os
Dented
Between 10mm + 30mm



21: Door osf
Scratched
Over 25mm Thru Paint



22: Door osf
Dented
2 Or Less UpTo 10mm



23: Wing osf
Scratched
UpTo 25mm Thru Paint



24: Wheel osf
Scratched
Over 50mm



25: Wing osf
Chipped
1 To 5



26: Switches And Controls
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK