



VEHICLE INSPECTION REPORT

HN60XBU

Volkswagen Tiguan 2.0 TDi Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/01/2011	Body Style	Estate	Last service miles	92,040
Year	2011	Keys	2	MOT Due	13/11/2026
Mileage	97,526 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	3	Doors	5
VIN	WVGZZZ5NZBW058795	Last service date	08/12/2025		

£90 ADDITIONAL FEE

SOME MOTS RECORDED IN KM

LAST SERVICE 08/12/2025 @ 92,040 MILES (3 SERVICES) Intermittent Eml car been plugged in and detected Throttle pedal position sensor A circuit range Engine knocking

Tyres

NSF	HIFLY	6.0mm
NSR	BUDGET	5.0mm
OSF	HIFLY	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
Over 5mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Dented
Over 30mm



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
Up To 25mm Thru Paint




14: Wheel osr
Scratched
Up To 50mm



15: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



16: Door osr
Chipped
Edge Chip



17: Door osf
Chipped
1 To 5



18: Door osf
Chipped
Edge Chip



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Poor Previous Repair
Rippled UpTo 30%



21: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	No Excessive Smoking	OK
Turbo Boosting	OK		
Parking Brake	OK		
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK