



VEHICLE INSPECTION REPORT

GU17EKB

Toyota Auris 1.8 Hybrid Excel TSS 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	17/03/2017	Colour	GREY	MOT Due	03/10/2026
Year	2017	VIN	SB1MS3JE60E321264	Gearbox	CVT
Mileage	110,918 Miles Warranted	Body Style	Hatchback	Gears	1
Fuel Type	HYBRID ELECTRIC	Keys	3	Doors	5


Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Seat Back Cover osf
Torn
Over 3mm



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Cracked
Over 25mm



5: Bumper Front Moulding
Broken
Replace



6: Wheel nsf
Scratched
Over 50mm



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Wing nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsf
Dented
Between 10mm + 30mm




11: Door nsr
Dented
Over 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Dented
With Paint Damage



15: B Post ns
Poor Previous Repair
Poor Paint




16: Qtr Panel osr
Dented
Over 30mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
Between 10mm + 30mm



20: Door osf
Chipped
Edge Chip



21: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK