



VEHICLE INSPECTION REPORT

LE69GCY

MG Mg Hs EXCLUSIVE DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/02/2020	Body Style	Estate	Last service miles	51,780
Year	2020	Keys	2	MOT Due	09/04/2027
Mileage	55,088 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Electronic / Online	Gears	7
Colour	BLACK	Number of stamps	1	Doors	5
VIN	SDPA2CBFDKN010842	Last service date	10/04/2026		

£90 ADDITIONAL FEE

NO GREEN SLIP

TIMING BELT CHANGED 10/04/2026 @ 51,780 MILES.

LAST SERVICE 10/04/2026 @ 51,780 MILES (1 SERVICE, MAIN DEALER - CONFIRMED BY CAFFYNS MG ASHFORD) Intermittent engine rattle

Eml light is on car has been plugged in and detects transmission control system, shift fork d stuck and invalid data received from park brake control

Tyre sensors faulty

Acc unavailable

Hill descent fault

Emergency assist brake unavailable

Tyres		
NSF	MICHELIN	Damaged
NSR	MICHELIN	5.0mm
OSF	MICHELIN	Damaged
OSR	MICHELIN	5.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos



Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5




2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Chipped
1 To 5



4: Wheel osr
Scratched
Over 50mm



5: Door osr
Chipped
Edge Chip



6: Qtr Panel osr
Dented
Between 10mm + 30mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5



11: Wheel nsf
Scratched
Over 50mm



12: Wing nsf
Chipped
1 To 5



13: Bumper Front
Scratched
25 to 100mm Thru Paint




14: Bonnet
Chipped
1 To 5



15: Screen Front
Cracked
Replace



16: Boot Lid
Dented
2 Or Less Up To 10mm



17: A Post os
Chipped
1 To 5



18: Bumper Front
Chipped
Multiple Chips



19: Switches And Controls
Broken
Replace



20: Tyre osf
Damaged
Replace



21: Tyre nsf
 Damaged
 Replace

Interior

Carpet Condition
 Seat Condition

Average
 Average

Upholstery Condition
 Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		