



VEHICLE INSPECTION REPORT

RX66OBE

Peugeot 2008 1.2 PureTech Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	20/09/2016	Body Style	Hatchback	Last service miles	57,150
Year	2016	Keys	2	MOT Due	01/04/2027
Mileage	76,630 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	7	Doors	5
VIN	VF3CUHMZ6GY116145	Last service date	30/03/2024		

Last Service - 30.03.24 at 57150 miles (7 services) Rattle from exhaust/ Heath shield

Tyres


NSF	BUDGET	6.0mm
NSR	OVATION	5.0mm
OSF	BUDGET	6.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Service indicator
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Other
N/A
N/A



3: Other
N/A
N/A



4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Scratched
UpTo 25mm Thru Paint




8: Wheel nsf
Scratched
Over 50mm




9: A Post ns
Chipped
1 To 5



10: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




11: Door nsf
Scratched
Over 25mm Thru Paint



12: Door nsr
Chipped
Edge Chip



13: Door nsr
Dented
Between 10mm + 30mm



14: Wheel nsr
Scratched
Over 50mm




15: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Tailgate
Scratched
Over 25mm Thru Paint



18: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



19: B Post os
Dented
2 Or Less UpTo 10mm



20: Qtr Panel osr
Dented
Between 10mm + 30mm



21: Qtr Panel osr
Chipped
1 To 5



22: Wheel osr
Scratched
Over 50mm




23: Door osr
Chipped
1 To 5



24: Door osr
Chipped
Edge Chip



25: Door osf
Chipped
Edge Chip



26: Door osf
Dented
Between 10mm + 30mm



27: Wing osf
Chipped
1 To 5



28: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK