



VEHICLE INSPECTION REPORT

GU11XME

Hyundai I30 1.6 CRDi Comfort 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/03/2011	Body Style	Estate	Last service miles	22,189
Year	2011	Keys	2	MOT Due	01/04/2027
Mileage	56,445 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	7	Doors	5
VIN	TMADB81SLBJ039008	Last service date	23/03/2018		

£100 ADDITIONAL FEE

Last Service - 23.03.2018 at 22189 miles (7 services 6 main dealer services)

Low clutch

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Screen Front
Chipped
UpTo 10mm



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Poor Previous Repair
Rippled UpTo 30%



17: Door osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Chipped
1 To 5



20: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



21: Other
N/A
N/A

22: Roof Lining
Scuffed
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK