



VEHICLE INSPECTION REPORT

GP24FSK

Kia Sportage 1.6T GDi 157 48V ISG 3 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/08/2024	Body Style	Estate	Last service miles	10,057
Year	2024	Keys	2	MOT Due	27/08/2027
Mileage	10,516 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	7
Colour	RED	Number of stamps	2	Doors	5
VIN	U5YPV81BVSL334080	Last service date	14/08/2026		

Last Service - 14.08.2026 at 10057 miles (2 main dealer services)

Tyres


NSF	CONTINENTAL	Damaged
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Tyre nsf
Damaged
Replace



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
UpTo 25mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
UpTo 25mm Thru Paint




7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Door osr
Chipped
Edge Chip



10: Door osr
Dented
Between 10mm + 30mm



11: Door osf
Chipped
Edge Chip



12: Wing osf
Chipped
1 To 5



13: A Post os
Scratched
Over 25mm Thru Paint



14: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK