



VEHICLE INSPECTION REPORT

SG18TOV

Renault Kadjar 1.2 TCE Signature S Nav 5dr EDC

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
4

Details

Reg. date	20/03/2018	Colour	BLUE	MOT Due	21/04/2027
Year	2018	VIN	VF1RFE00659920428	Gearbox	AUTOMATIC
Mileage	36,658 Miles Warranted	Body Style	Hatchback	Gears	7
Fuel Type	PETROL	Keys	2	Doors	5

Tyres

NSF	DAVANTI	4.0mm
NSR	DAVANTI	4.0mm
OSF	DAVANTI	4.0mm
OSR	BARUM	5.0mm


Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Door Moulding nsr
Broken
Replace



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
Edge Chip



10: Tailgate
Chipped
1 To 5



11: Qtr Panel osr
Chipped
1 To 5



12: Wheel osr
Scratched
Over 50mm



13: Door nsr
Dented
With Paint Damage



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
Edge Chip



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm



18: Aperture Seal osf
Broken
Replace



19: Seat Back Cover osf
Scuffed
Over 25mm



20: Bonnet
Dented
Hail - Moderate

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK