



VEHICLE INSPECTION REPORT

GV10NFC

Ford Fiesta 1.25 Zetec 3dr [82]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/07/2010	Body Style	Hatchback	Last service miles	84,327
Year	2010	Keys	1	MOT Due	19/07/2027
Mileage	93,040 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	12	Doors	3
VIN	WF0GXXGAJGAU69909	Last service date	11/04/2025		

£100 ADDITIONAL FEE

Last Service - 11.4.25 at 84327 miles (12 services (3 main dealer)) Steering knocking
Exhaust blowing

Tyres

NSF	BUDGET	5.0mm
NSR	JOYROAD	4.0mm
OSF	BUDGET	5.0mm
OSR	ROADSTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Aperture Seal of
Broken
Replace



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Fogdriving Lamp osf
Broken
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: A Post ns
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
Between 10mm + 30mm



10: Wheel nsr
Scratched
Over 50mm



11: B Post ns
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Dented
With Paint Damage



13: Bumper Reflector nsr
Broken
Replace



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Tailgate
Scratched
Over 25mm Thru Paint



16: Roof
Dented
Over 30mm



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Poor Previous Repair
Poor Paint



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK