



VEHICLE INSPECTION REPORT

GV20JYW

Renault ZOE 100kW i GT Line R135 50kWh Rapid Charge 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/08/2020	Body Style	Hatchback	Last service miles	34,301
Year	2020	Keys	2	MOT Due	Expired
Mileage	40,361 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Service Book	Gears	1
Colour	WHITE	Number of stamps	4	Doors	5
VIN	VF1AG000265812460	Last service date	02/10/2024		

£65 ADDITIONAL FEE

Last Service - 02.10.2024 at 34301 miles (4 main dealer services)

Battery Owned

Tyres


NSF	MICHELIN	3.0mm
NSR	MICHELIN	3.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
1 To 5




5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



7: Bumper Rear
Chipped
Multiple Chips



8: Bumper Rear
Chipped
Multiple Chips



9: Wheel nsr
Scratched
Up To 50mm

No Image

10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Over 50mm

No Image

12: Door osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Dented
2 Or Less UpTo 10mm

No Image

14: Wing osf
Scratched
Over 25mm Not Thru Paint



15: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK