



VEHICLE INSPECTION REPORT

KT15HAO

Peugeot 3008 1.6 BlueHDi 120 Allure 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	22/05/2015	Colour	GREY	MOT Due	20/05/2027
Year	2015	VIN	VF30UBHZTFS130008	Gearbox	AUTOMATIC
Mileage	63,808 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	DIESEL	Keys	2	Doors	5

Ad blue message displayed

Tyres

NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Insecure
Action Required



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Tailgate
Scratched
UpTo 25mm Thru Paint



13: C Post os
Dented
Over 30mm



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Chipped
Edge Chip



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK