



VEHICLE INSPECTION REPORT

GU62KCA

BMW 1 Series 118d Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/09/2012	Body Style	Hatchback	Last service miles	53,341
Year	2012	Keys	2	MOT Due	29/09/2026
Mileage	110,344 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	BLUE	Number of stamps	3	Doors	5
VIN	WBA1C12020VS70376	Last service date	13/06/2016		

£90 ADDITIONAL FEE

Last Service - 13.06.16 at 53341 miles (3 services)

Tyres

NSF	HABILEAD	5.0mm
NSR	HABILEAD	5.0mm
OSF	HABILEAD	5.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Qtr Panel osr
Chipped
1 To 5




9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Corroded
Light



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Chipped
1 To 5



14: Wing nsf
Dented
Between 10mm + 30mm



15: Wing nsf
Scratched
UpTo 25mm Thru Paint



16: Wheel nsf
Corroded
Light



17: Bumper Front
Scratched
UpTo 25mm Thru Paint



18: Bumper Front
Chipped
Multiple Chips



19: Bonnet
Chipped
1 To 5



20: A Post os
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm

22: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK