



VEHICLE INSPECTION REPORT

DL64HDA

Vauxhall Corsa 1.4 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/01/2015	Body Style	Hatchback	Last service miles	139,044
Year	2015	Keys	2	MOT Due	18/01/2027
Mileage	140,976 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	11	Doors	5
VIN	W0L0SDL68E4334793	Last service date	02/01/2026		

Last Service - 02.01.26 at 139044 miles (11 services (7 main dealer)) Front suspension knocking

Tyres


NSF	FALKEN	4.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm



2: Seat Back Cover osf
Scuffed
Over 25mm



3: Seat Back Cover osf
Torn
Over 3mm



4: Bonnet
Dented
Between 10mm + 30mm



5: Bonnet
Chipped
Multiple Chips



6: Bumper Front
Cracked
Over 25mm



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Chipped
1 To 5



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Door nsf
Dented
Between 10mm + 30mm



11: Door nsf
Scratched
UpTo 25mm Thru Paint



12: Door nsr
Chipped
Multiple Chips



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Tailgate
Scratched
Over 25mm Thru Paint



17: B Post ns
Scratched
Over 25mm Thru Paint



18: Qtr Panel osr
Dented
Between 10mm + 30mm



19: Qtr Panel osr
Chipped
1 To 5



20: Wheel osr
Scratched
Over 50mm



21: Door osr
Scratched
Over 25mm Thru Paint



22: Door osf
Scratched
Over 25mm Thru Paint



23: Wing osf
Chipped
1 To 5



24: Wheel osf
Scratched
Over 50mm



25: Tailgate
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK