

VEHICLE INSPECTION REPORT

GX16XWE

Volkswagen Polo 1.2 TSI SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	18/03/2016	Colour	GREY	MOT Due	17/03/2027
Year	2016	VIN	WVWZZZ6RZGU037529	Gearbox	MANUAL
Mileage	107,856 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	PETROL	Keys	2	Doors	5

Front suspension knocking



Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Rusted
Over 5mm



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




6: Flasher Side Repeater ns
Broken
Replace



7: Door nsf
Dented
Over 30mm



8: Door nsf
Chipped
Edge Chip



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Dented
With Paint Damage



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Over 50mm



15: Sill os
Scratched
Over 25mm Thru Paint



16: Door osr
Chipped
1 To 5



17: Door osf
Poor Previous Repair
Poor Paint



18: Door Mirror Assy osf
Broken
Replace



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK