



VEHICLE INSPECTION REPORT

GU14YYS

Citroen DS4 1.6 e-HDi 115 DStyle 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/04/2014	Keys	2	CAP Clean	£1,575.00
Year	2014	Service history	Yes	CAP Average	£1,175.00
Mileage	87,160 Miles Warranted	Service documents	Service Book	CAP Below	£775.00
Fuel Type	Diesel	Number of stamps	12	Gearbox	MANUAL
Colour	MAUVE/PURPLE	Last service date	05/05/2026	Gears	6
VIN	VF7NX9HD8EY520796	Last service miles	86,146	Doors	5
Body Style	Hatchback	MOT Due	06/03/2027		

last service 5/5/26 @ 86,146 miles (12 services 3 main dealer)
cambelt & water pump replaced on 2/5/24 @ 79,679 miles Engine fault repair needed displays on dash

Tyres

NSF	SUNNY	5.0mm
NSR	SUNNY	5.0mm
OSF	SUNNY	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Seat Base Cover of
Scuffed
Over 25mm



2: Bonnet
Rusted
Over 5mm



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Door nsr
Scratched
UpTo 25mm Thru Paint




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Over 30mm



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Up To 25mm Thru Paint




14: Qtr Panel osr
Dented
With Paint Damage




15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
Edge Chip



17: Door osf
Dented
Between 10mm + 30mm



18: Door osf
Chipped
Edge Chip



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: B Post ns
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK