

VEHICLE INSPECTION REPORT

GY17NGO

Kia Sportage 2.0 CRDi KX-4 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 Grape
		V5	Present		
Details					
Reg. date	21/04/2017	Keys	2	CAP Clean	£6,350.00
Year	2017	Service history	Yes	CAP Average	£5,475.00
Mileage	115,877 Miles Warranted	Service documents	Service Book	CAP Below	£4,650.00
		Number of stamps	7	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	08/12/2023	Gears	6
Colour	SILVER	Last service miles	90,853		
VIN	U5YPH813SHL232014	MOT Due	08/01/2026		
Body Style	Estate				

£100 ADDITIONAL FEE Last service 08/12/2023 @ 90853 miles (7 MAIN DEALER SERVICES) EML LIGHT ON

Ту	res
NS	SF.

NSF	DAVANTI	4.0mm	
NSR	AVON	5.0mm	
OSF	DAVANTI	5.0mm	
OSR	AVON	5.0mm	
Spare			

Features

- Bluetooth connection
- Navigation systemTelephone
- Electric sunroof
- Electrically adjustable passenger Front armrest seat
- Rear headrests
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Metallic Paint
- Tyre pressure monitorAlloy wheels

- Front parking sensor
- Rear parking sensor
 Body coloured bumpers
- Climate control
- Front electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electric door mirrors
 Electrically adjustable drivers seat
 Rear electric windows
- Passenger airbag
- Remote central locking

Photos






















Condition Check



Damage Photos



1: Wheel osf Scratched Over 50mm



2: Door Moulding osf Missing Replace



3: Door Moulding osr Missing Replace



4: Door osf Chipped Edge Chip



5: Wheel osr Corroded Light



6: Qtr Panel osr Scratched Over 25mm Not Thru Paint



7: Bumper Rear Moulding Broken Replace



8: Wheel nsr Corroded Light



9: Door Moulding nsr Missing Replace



10: Door Moulding nsf Missing Replace



11: Door nsrChipped1 To 5



12: Wheel nsf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		