



VEHICLE INSPECTION REPORT

TGZ3705

Vauxhall Grandland X 1.2 Turbo SRi Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/01/2021	Body Style	Hatchback	Last service miles	38,311
Year	2021	Keys	2	MOT Due	Expired
Mileage	46,865 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	4	Doors	5
VIN	W0VZRHNS0M6806001	Last service date	30/07/2025		

£100 ADDITIONAL FEE

LAST SERVICE 30/07/2025 @ 38,311 MILES (4 SERVICES, 3 MAIN DEALER) Service spanner displayed
Gearbox faulty

Tyres

NSF	LAUFENN	3.0mm
NSR	ACCELERA	4.0mm
OSF	BUDGET	6.0mm
OSR	LAUFENN	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Door nsf
Poor Previous Repair
Rippled Up To 30%




4: B Post ns
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Dented
Between 10mm + 30mm



11: Door osr
Chipped
1 To 5



12: Door osf
Dented
2 Or Less UpTo 10mm



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Dented
Over 30mm



15: Roof
Scratched
Over 25mm Thru Paint



16: Qtr Panel Arch Extension ns
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK