



VEHICLE INSPECTION REPORT

LX66HHL

Mitsubishi Outlander 2.2 DI-D 4 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	27/01/2017	Body Style	Estate	Last service miles	65,935
Year	2017	Keys	2	MOT Due	26/01/2027
Mileage	70,265 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Electronic / Online	Gears	6
Colour	BLACK	Number of stamps	1	Doors	5
VIN	JMAXLGF6WHZ400280	Last service date	13/01/2026		

£100 ADDITIONAL FEE

Last service 13/01/2026 at 65,935 miles- 1 service confirmed by T&L Garage Services, St Leonards on Sea
Noisy engine

Tyres


NSF	YOKOHAMA	3.0mm
NSR	MICHELIN	2.5mm
OSF	DUNLOP	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osf
Dented
Between 10mm + 30mm



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint




8: Qtr Panel nsr
Chipped
1 To 5



9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Door nsf
Dented
2 Or Less UpTo 10mm



11: Wing nsf
Dented
Over 30mm



12: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint




13: Bonnet
Chipped
1 To 5



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Roof
Chipped
1 To 5



16: Door osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		