



VEHICLE INSPECTION REPORT

WR15DWJ

Volvo V40 D2 ES 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	21/04/2015	Colour	SILVER	MOT Due	05/04/2027
Year	2015	VIN	YV1MV848BF2243419	Gearbox	AUTOMATIC
Mileage	64,059 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	DIESEL	Keys	2	Doors	5

Tyres

NSF	HANKOOK	Damaged
NSR	HANKOOK	5.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: A Post ns
Chipped
1 To 5




5: Door nsf
Chipped
1 To 5



6: Door nsr
Poor Previous Repair
Poor Paint



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
Edge Chip



13: Door osf
Dented
Between 10mm + 30mm



14: Door osf
Chipped
Edge Chip



15: Wing osf
Poor Previous Repair
Poor Paint



16: Wheel osf
Scratched
Over 50mm



17: Tyre nsf
Damaged
Replace



18: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No