



VEHICLE INSPECTION REPORT

HK15KWC

Hyundai Santa Fe 2.2 CRDi Premium 5dr [7 Seats]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/05/2015	Body Style	Estate	Last service miles	142,597
Year	2015	Keys	1	MOT Due	08/07/2027
Mileage	154,007 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	9	Doors	5
VIN	KMHSX81XNFU484073	Last service date	06/10/2025		

Last Service - 06.10.2025 at 142597 miles (9 Services)
Strat to blow black smoke when Accelerating

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
1 To 5



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Corroded
Light



5: Qtr Panel osr
Chipped
1 To 5



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Bumper Rear
Chipped
Multiple Chips



8: Door nsr
Chipped
1 To 5




9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Corroded
Light



11: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint




12: Bonnet
Dented
Over 30mm



13: Bumper Front
Chipped
Multiple Chips



14: Roof
Dented
With Paint Damage



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK